

Dead Weight Creep Test Rig

Direct Loading

500 N load set

Integrated travel gauges

Pneumatic Lifting and Loading
of weight set.

Optional Tempering Chamber

Camera System recommended



Dead Weight Creep Test Rig 10:1 Lever Loading

500 N load set
5000 kN maximum loading

Integrated travel gauges

Pneumatic Lifting and Loading
of weight set.

Optional Tempering Chamber

Camera System recommended

